



RECEIVED  
APR 01 2011  
Utilities Div.

**Aaron Reardon**  
County Executive

3000 Rockefeller Ave., M/S 607  
Everett, WA 98201 – 4046

(425) 388-6537  
FAX (425) 388-6670

March 30, 2011

James Kelly  
Public Works Director  
City of Arlington  
238 N Olympic Ave  
Arlington WA 98233-1337

**RE: Bridge Inspection Reports**

Dear Mr. Kelly:

Under Aid Agreement No. 200109250605 (RR7616) between Snohomish County and the City of Arlington, we have completed routine inspections for three bridges owned by the city. Attached please find the inspection reports. Brief summaries are as follows:

- ARL-01, South Slough – Smokey Point Boulevard, Structure ID 08084500
  - ◆ Condition: No significant change noted.
  - ◆ Repair recommendations: None noted.
  
- ARL-02, Portage Creek – Smokey Point Boulevard, Structure ID 08226400
  - ◆ Condition: No significant change noted.
  - ◆ Repair recommendations:
    - Seal pavement seat to limit water intrusion into arch fill.
    - Control runoff at SE embankment.
    - Repair guardrail damage at corners of bridge.
  
- ARL-03, Portage Creek - Crown Ridge Boulevard, Structure ID 08825200
  - ◆ Condition: No significant change noted.
  - ◆ Repair recommendations:
    - Repair loose fascia board @ S overhang.
    - Repair trip hazard at ea. corner typ.

If you have any questions please do not hesitate to contact me at (425) 388-3196,  
Kinyan.Lui@snoco.org or John Heighway, Lead Bridge Inspector, at (425) 388-3195,  
John.Heighway@snoco.org.

Sincerely,



Kinyan Lui, P.E.  
Bridge Group Supervisor

KL:cdw

Attachments: Bridge Inspection Reports

Cc: Bruce DuVall, Snohomish County  
Grant Griffin, WSDOT Local Programs Bridge Engineer