

# City of Arlington Preliminary Site Assessment

## SITE INFORMATION




Figure 1. Location Map.

Parcel Number: 00426400001800

Parcel Area (acres): 0

Site Address: UNKNOWN UNKNOWN

Property Owner: RUSHER NANCY C

Maps and GIS data are distributed "AS-IS" without warranties of any kind, either express or implied, including but not limited to warranties of suitability for a particular purpose or use. Map data are compiled from a variety of sources which may contain errors and users who rely upon the information do so at their own risk. Users agree to indemnify, defend, and hold harmless the City of Arlington for any and all liabilities of any nature arising out of or resulting from the lack of accuracy or correctness of the data, or the use of the data presented in the maps.

# SITE CHARACTERISTICS

| Percent Saturate | d/Wetland Soils Onsite |              |                             | Low:    | .===   |
|------------------|------------------------|--------------|-----------------------------|---------|--------|
|                  | -                      |              | USGS Aquifer                | Medium: |        |
|                  | 0 to 8%                | 38.9%        | Sensitivity                 | High:   | 100.0% |
| Slopes Onsite    | 8 to 12%               | 12.9%        | Drinking Water Well Onsite? |         | No     |
|                  | 12 to 15%              | 1.9%<br>5.4% |                             |         |        |
|                  | 15 to 20%              |              | Soil Contamination          | No      |        |
|                  | 20 to 33%              | 10.8%        | UST Onsite?                 | No      |        |
|                  | > 33%                  | 30.2%        | Septic System Onsite?       |         | No     |

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

## PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

| Infiltrating<br>Bioretention Cell/Swale | 64% | Permeable Pavement   | 61%                     | Underground Detention and Treatment | On a site by site basis |
|---|-----|----------------------|-------------------------|-------------------------------------|-------------------------|
| Infiltrating<br>Bioretention Planter    | 64% | Ponds and Wetlands   | On a site by site basis | Aboveground Sand Filtration         | On a site by site basis |
| Non-Infiltrating<br>Bioretention        | 61% | Basic Filter Strips  | On a site by site basis | Infiltration BMPs                   | On a site by site basis |
|   |     | Biofiltration Swales | On a site by site basis | Dispersion BMPs                     | On a site by site basis |

# **CRITICAL AREAS MAP** Fhodplan Mode to tr Slepe i

