


# City of Arlington Preliminary Site Assessment

## SITE INFORMATION



#### Figure 1. Location Map.

### SITE CHARACTERISTICS

Percent Saturated/Wetland Soils Onsite				Low:	
		_	USGS Aquifer	Medium:	100.0%
	0 to 8%	83.4%	Sensitivity	High:	
Slopes Onsite	8 to 12%	4.6%	Drinking Water Well Onsite? Soil Contamination Area Onsite?		No
	12 to 15%	2.0%			
	15 to 20%	3.1%			No
	20 to 33%	5.9%	UST Onsite?		No
	> 33%	1.1%	Septic System Onsit	No	

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

## PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

Infiltrating Bioretention Cell/Swale	17%	Permeable Pavement	12%	Underground Detention and Treatment	On a site by site basis
Infiltrating Bioretention Planter	17%	Ponds and Wetlands	On a site by site basis	Aboveground Sand Filtration	On a site by site basis
Non-Infiltrating Bioretention	17%	Basic Filter Strips	On a site by site basis	Infiltration BMPs	On a site by site basis
		<b>Biofiltration Swales</b>	On a site by site basis	Dispersion BMPs	On a site by site basis

