

# City of Arlington Preliminary Site Assessment

### SITE INFORMATION




Figure 1. Location Map.

#### SITE CHARACTERISTICS

Percent Saturated/Wetland Soils Onsite				Low:	,
			USGS Aquifer	Medium:	0.5%
Slopes Onsite	0 to 8%	99.6%	Sensitivity	High:	99.5%
	8 to 12%	0.4%	Drinking Water Wel	l Onsite?	No
	12 to 15%				
	15 to 20%		Soil Contamination Area Onsite?		No
	20 to 33%		UST Onsite?		No
	> 33%		Septic System Onsite	Yes	

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

#### PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

Infiltrating Bioretention Cell/Swale	0%	Permeable Pavement	On a site by site basis	Underground Detention and Treatment	On a site by site basis
Infiltrating Bioretention Planter	0%	Ponds and Wetlands	On a site by site basis	Aboveground Sand Filtration	On a site by site basis
Non-Infiltrating Bioretention	0%	Basic Filter Strips	On a site by site basis	Infiltration BMPs	On a site by site basis
		<b>Biofiltration Swales</b>	On a site by site basis	Dispersion BMPs	On a site by site basis

## CRITICAL AREAS MAP

