

City of Arlington Preliminary Site Assessment

SITE INFORMATION



Figure 1. Location Map.

Parcel Number:	00621300006700
Parcel Area (acres):	0

Site Address: 17731 33RD AVE NE

Property Owner: OHAGEN P J

Maps and GIS data are distributed "AS-IS" without warranties of any kind, either express or implied, including but not limited to warranties of suitability for a particular purpose or use. Map data are compiled from a variety of sources which may contain errors and users who rely upon the information do so at their own risk. Users agree to indemnify, defend, and hold harmless the City of Arlington for any and all liabilities of any nature arising out of or resulting from the lack of accuracy or correctness of the data, or the use of the data presented in the maps.

SITE CHARACTERISTICS

Percent Saturated/Wetland Soils Onsite			USGS Aquifer	Low: Medium:	100.0%
0 to 8% 8 to 12% 12 to 15% 15 to 20% 20 to 33% > 33%	0 to 8%	100.0%	Sensitivity	High:	
	8 to 12%		Drinking Water Well Onsite?		No
	12 to 15%				
	15 to 20%		Soil Contamination	Area Onsite?	No
	20 to 33%		UST Onsite?		No
	> 33%		Septic System Onsit	e?	Yes

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

Infiltrating	On a site by	Permeable Pavement	On a site by	Underground Detention	On a site by
Bioretention Cell/Swale	site basis		site basis	and Treatment	site basis
Infiltrating	On a site by	Ponds and Wetlands	On a site by	Aboveground Sand	On a site by
Bioretention Planter	site basis		site basis	Filtration	site basis
Non-Infiltrating	On a site by	Basic Filter Strips	On a site by	Infiltration BMPs	On a site by
Bioretention	site basis		site basis		site basis
		Biofiltration Swales	On a site by	Dispersion BMPs	On a site by
			site basis		site basis



