

# City of Arlington Preliminary Site Assessment

## SITE INFORMATION



#### Figure 1. Location Map.

### SITE CHARACTERISTICS

Percent Saturated/Wetland Soils Onsite				Low:	100.0%
			USGS Aquifer	Medium:	
	0 to 8%	35.9%	Sensitivity	High:	
Slopes Onsite	8 to 12%	7.8%	Drinking Water Well Onsite? Soil Contamination Area Onsite?		No
	12 to 15%	9.2%			
	15 to 20%	16.4% 30.6%			No
	20 to 33%		UST Onsite?		No
	> 33%		Septic System Onsite?		No

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

## PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

Infiltrating Bioretention Cell/Swale	64%	Permeable Pavement	56%	Underground Detention and Treatment	On a site by site basis
Infiltrating Bioretention Planter	64%	Ponds and Wetlands	On a site by site basis	Aboveground Sand Filtration	On a site by site basis
Non-Infiltrating 64% Bioretention		Basic Filter Strips	On a site by site basis	Infiltration BMPs	On a site by site basis
		Biofiltration Swales	On a site by site basis	Dispersion BMPs	On a site by site basis



