

City of Arlington Preliminary Site Assessment

SITE INFORMATION




Figure 1. Location Map.

SITE CHARACTERISTICS

Percent Saturated/Wetland Soils Onsite		0.0001101529		Low:	100.0%
		0695	USGS Aquifer	Medium:	
	0 to 8%	18.3%	Sensitivity	High:	
Slopes Onsite	8 to 12%	14.6%	Drinking Water Wel	l Onsite?	No
	12 to 15%	8.3%			
	15 to 20%	17.1%	Soil Contamination Area Onsite?		No
	20 to 33%	41.3%	UST Onsite?		No
	> 33%	0.4%	Septic System Onsite?		No

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

Infiltrating Bioretention Cell/Swale	82%	Permeable Pavement	67%	Underground Detention and Treatment	On a site by site basis
Infiltrating Bioretention Planter	82%	Ponds and Wetlands	On a site by site basis	Aboveground Sand Filtration	On a site by site basis
Non-Infiltrating Bioretention	82%	Basic Filter Strips	On a site by site basis	Infiltration BMPs	On a site by site basis
		Biofiltration Swales	On a site by site basis	Dispersion BMPs	On a site by site basis

