


# City of Arlington Preliminary Site Assessment

### SITE INFORMATION



#### Figure 1. Location Map.

#### SITE CHARACTERISTICS


Percent Saturated	/Wetland Soils Onsite			Low:	
			USGS Aquifer	Medium:	100.0%
	0 to 8%	53.8%	Sensitivity	High:	
Slopes Onsite	8 to 12%	7.6%	Drinking Water Well Onsite? Soil Contamination Area Onsite?		No
	12 to 15%	3.7%			
	15 to 20%	5.0%			No
	20 to 33%	14.2%	UST Onsite?		No
	> 33%	15.7%	Septic System Onsite?		Yes

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

#### PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

Infiltrating Bioretention Cell/Swale	0%	Permeable Pavement	0%	Underground Detention and Treatment	On a site by site basis
Infiltrating Bioretention Planter	0%	Ponds and Wetlands	23%	Aboveground Sand Filtration	23%
Non-Infiltrating Bioretention	0%	Basic Filter Strips	On a site by site basis	Infiltration BMPs	23%
		Biofiltration Swales	On a site by site basis	Dispersion BMPs	23%

## CRITICAL AREAS MAP



### **UTILITIES MAP**

