

City of Arlington Preliminary Site Assessment

SITE INFORMATION




Figure 1. Location Map.

SITE CHARACTERISTICS

Percent Saturated	d/Wetland Soils Onsite			Low:	26.8%
			USGS Aquifer Sensitivity	Medium:	73.2%
Slopes Onsite	0 to 8%	35.9%		High:	
	8 to 12%	31.9%	Drinking Water Wel	l Onsite?	No
	12 to 15%	13.6%			
	15 to 20%	8.3%	Soil Contamination Area Onsite?		No
	20 to 33%	6.4%	UST Onsite?		No
	> 33%	3.9%	Septic System Onsite?		Yes

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

Infiltrating Bioretention Cell/Swale	0%	Permeable Pavement	1%	Underground Detention and Treatment	On a site by site basis
Infiltrating Bioretention Planter	0%	Ponds and Wetlands	On a site by site basis	Aboveground Sand Filtration	On a site by site basis
Non-Infiltrating Bioretention	0%	Basic Filter Strips	On a site by site basis	Infiltration BMPs	On a site by site basis
		Biofiltration Swales	On a site by site basis	Dispersion BMPs	On a site by site basis

