

City of Arlington Preliminary Site Assessment

SITE INFORMATION




Figure 1. Location Map.

SITE CHARACTERISTICS

Percent Saturated/Wetland Soils Onsite				Low:	
			USGS Aquifer	Medium:	8.5%
	0 to 8%	89.5%	Sensitivity	High:	91.5%
Slopes Onsite	8 to 12%	3.9%	Drinking Water Well Onsite? Soil Contamination Area Onsite?		No
	12 to 15%	1.9%			
	15 to 20%	2.2%			No
	20 to 33%	2.0%	UST Onsite?		No
	> 33%	0.4%	Septic System Onsite?		No

127

E GILMAN AVE

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

Infiltrating Bioretention Cell/Swale	0%	Permeable Pavement	0%	Underground Detention and Treatment	On a site by site basis
Infiltrating Bioretention Planter	0%	Ponds and Wetlands	2%	Aboveground Sand Filtration	38%
Non-Infiltrating Bioretention	0%	Basic Filter Strips	On a site by site basis	Infiltration BMPs	38%
		Biofiltration Swales	On a site by site basis	Dispersion BMPs	38%

CRITICAL AREAS MAP

