


# City of Arlington Preliminary Site Assessment

## SITE INFORMATION



#### Figure 1. Location Map.

#### SITE CHARACTERISTICS

Percent Saturated/Wetland Soils Onsite				Low:	
			USGS Aquifer	Medium:	100.0%
	0 to 8%	74.3%	Sensitivity	High:	
Slopes Onsite	8 to 12%	4.5%	Drinking Water Well Onsite? Soil Contamination Area Onsite?		No
	12 to 15%	1.7%			
	15 to 20%	2.9%			No
	20 to 33%	6.3%	UST Onsite?		No
	> 33%	10.4%	Septic System Onsite?		No

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

### PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

Infiltrating Bioretention Cell/Swale	1%	Permeable Pavement	21%	Underground Detention and Treatment	On a site by site basis
Infiltrating Bioretention Planter	1%	Ponds and Wetlands	On a site by site basis	Aboveground Sand Filtration	On a site by site basis
Non-Infiltrating Bioretention	1%	Basic Filter Strips	On a site by site basis	Infiltration BMPs	On a site by site basis
		Biofiltration Swales	On a site by site basis	Dispersion BMPs	On a site by site basis

# **CRITICAL AREAS MAP**

