


# City of Arlington Preliminary Site Assessment

## SITE INFORMATION



#### Figure 1. Location Map.

### SITE CHARACTERISTICS

Percent Saturated	d/Wetland Soils Onsite			Low:	
		_	USGS Aquifer	Medium:	0.0%
	0 to 8%	91.6%	Sensitivity	High:	100.0%
Slopes Onsite	8 to 12%	3.2%	Drinking Water Well Onsite? Soil Contamination Area Onsite?		No
	12 to 15%	1.0%			
	15 to 20%	1.1%			No
	20 to 33%	1.8%	UST Onsite?		No
	> 33%	1.3%	Septic System Onsite?		No

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

## PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

Infiltrating Bioretention Cell/Swale	On a site by site basis	Permeable Pavement	On a site by site basis	Underground Detention and Treatment	On a site by site basis
Infiltrating Bioretention Planter	On a site by site basis	Ponds and Wetlands	19%	Aboveground Sand Filtration	19%
Non-Infiltrating Bioretention	0%	Basic Filter Strips	On a site by site basis	Infiltration BMPs	19%
		Biofiltration Swales	On a site by site basis	Dispersion BMPs	19%

