

## City of Arlington Preliminary Site Assessment

## SITE INFORMATION




Figure 1. Location Map.

## SITE CHARACTERISTICS

Percent Saturated	d/Wetland Soils Onsite			Low:	
			USGS Aquifer	Medium:	
	0 to 8%	54.1%	Sensitivity	High:	100.0%
Slopes Onsite	8 to 12%	14.3%	Drinking Water Well Onsite? Soil Contamination Area Onsite?		No
	12 to 15%	8.1%			
	15 to 20%	10.6%			No
	20 to 33%	8.5%	UST Onsite?		No
	> 33%	4.4%	Septic System Onsite?		No

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

## PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

Infiltrating Bioretention Cell/Swale	On a site by site basis	Permeable Pavement	On a site by site basis	Underground Detention and Treatment	On a site by site basis
Infiltrating Bioretention Planter	On a site by site basis	Ponds and Wetlands	50%	Aboveground Sand Filtration	On a site by site basis
Non-Infiltrating Bioretention	0%	Basic Filter Strips	On a site by site basis	Infiltration BMPs	On a site by site basis
		Biofiltration Swales	On a site by site basis	Dispersion BMPs	On a site by site basis

