

# City of Arlington Preliminary Site Assessment

## SITE INFORMATION




Figure 1. Location Map.

#### SITE CHARACTERISTICS

Percent Saturated/Wetland Soils Onsite		0.1429430851		Low:	100.0%
		7	USGS Aquifer	Medium:	
	0 to 8%	51.9%	Sensitivity	High:	
Slopes Onsite	8 to 12%	15.0%	Drinking Water Well Onsite? Soil Contamination Area Onsite?		No
	12 to 15%	7.3%			
	15 to 20%	7.8%			No
	20 to 33%	8.4%	UST Onsite?		No
	> 33%	9.6%	Septic System Onsite?		No

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

### PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

Infiltrating Bioretention Cell/Swale	0%	Permeable Pavement	0%	Underground Detention and Treatment	On a site by site basis
Infiltrating Bioretention Planter	0%	Ponds and Wetlands	18%	Aboveground Sand Filtration	On a site by site basis
Non-Infiltrating Bioretention	0%	Basic Filter Strips	On a site by site basis	Infiltration BMPs	On a site by site basis
		Biofiltration Swales	On a site by site basis	Dispersion BMPs	On a site by site basis

# **CRITICAL AREAS MAP**

