

City of Arlington Preliminary Site Assessment

SITE INFORMATION



Figure	1.	Location	Man.
LISUIC		LOCULIOII	IVIUP.

Parcel Number: 31051700300700

Parcel Area (acres): 6

Site Address: 19324 23RD AVE NE

Property Owner: WOLFE DENNIS & JANICE

Maps and GIS data are distributed "AS-IS" without warranties of any kind, either express or implied, including but not limited to warranties of suitability for a particular purpose or use. Map data are compiled from a variety of sources which may contain errors and users who rely upon the information do so at their own risk. Users agree to indemnify, defend, and hold harmless the City of Arlington for any and all liabilities of any nature arising out of or resulting from the lack of accuracy or correctness of the data, or the use of the data presented in the maps.

SITE CHARACTERISTICS

Percent Saturated/Wetland Soils Onsite			Low:	
		USGS Aquifer	Medium:	
0 to 8%	91.7%	Sensitivity	High:	100.0%
8 to 12%	6.7%	Drinking Water Well Onsite?		No
12 to 15%	1.3%			
15 to 20%	0.3%	Soil Contamination	No	
20 to 33%		UST Onsite?		No
> 33%		Septic System Onsit	e?	Yes
	0 to 8% 8 to 12% 12 to 15% 15 to 20% 20 to 33%	0 to 8% 91.7% 8 to 12% 6.7% 12 to 15% 1.3% 15 to 20% 0.3% 20 to 33%	USGS Aquifer Sensitivity 0 to 8% 91.7% 8 to 12% 6.7% Drinking Water Well 12 to 15% 1.3% Soil Contamination 20 to 33% UST Onsite?	USGS Aquifer Sensitivity 0 to 8% 91.7% 6.7% Drinking Water Well Onsite? 12 to 15% 1.3% Soil Contamination Area Onsite? USGS Aquifer Medium: High: Sensitivity High: UST Onsite?

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

Infiltrating Bioretention Cell/Swale	0%	Permeable Pavement	0%	Underground Detention and Treatment	On a site by site basis
Infiltrating Bioretention Planter	0%	Ponds and Wetlands	68%	Aboveground Sand Filtration	66%
Non-Infiltrating Bioretention	0%	Basic Filter Strips	On a site by site basis	Infiltration BMPs	66%
		Biofiltration Swales	On a site by site basis	Dispersion BMPs	66%



