

City of Arlington Preliminary Site Assessment

SITE INFORMATION




Figure 1. Location Map.


SITE CHARACTERISTICS

Percent Saturated	d/Wetland Soils Onsite			Low:	
			USGS Aquifer	Medium:	
Slopes Onsite	0 to 8%	99.8%	Sensitivity Drinking Water Wel	High:	100.0%
	8 to 12%	0.2%		Onsite?	No
	12 to 15%				
	15 to 20%		Soil Contamination Area Onsite?		No
	20 to 33%		UST Onsite?		No
	> 33%		Septic System Onsite?		Yes

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

Infiltrating Bioretention Cell/Swale	21%	Permeable Pavement	21%	Underground Detention and Treatment	On a site by site basis
Infiltrating Bioretention Planter	21%	Ponds and Wetlands	21%	Aboveground Sand Filtration	21%
Non-Infiltrating Bioretention	0%	Basic Filter Strips	On a site by site basis	Infiltration BMPs	21%
		Biofiltration Swales	On a site by site basis	Dispersion BMPs	21%



UTILITIES MAP		
		-23RD AVE-NE
		192ND ST NE