

## City of Arlington Preliminary Site Assessment

## SITE INFORMATION




Figure 1. Location Map.

## SITE CHARACTERISTICS

Percent Saturated	/Wetland Soils Onsite			Low:	
	-		USGS Aquifer	Medium:	31.5%
	0 to 8%	79.7%	Sensitivity	High:	68.5%
Slopes Onsite	8 to 12%	5.6%	Drinking Water Well Onsite? Soil Contamination Area Onsite?		No
	12 to 15%	2.7%			
	15 to 20%	4.1%			No
	20 to 33%	7.6%	UST Onsite?		No
	> 33%	0.3%	Septic System Onsite?		Yes

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

## PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

Infiltrating Bioretention Cell/Swale	On a site by site basis	Permeable Pavement	On a site by site basis	Underground Detention and Treatment	On a site by site basis
Infiltrating Bioretention Planter	On a site by site basis	Ponds and Wetlands	1%	Aboveground Sand Filtration	1%
Non-Infiltrating Bioretention	0%	Basic Filter Strips	On a site by site basis	Infiltration BMPs	1%
		Biofiltration Swales	On a site by site basis	Dispersion BMPs	1%

