


# City of Arlington Preliminary Site Assessment

## SITE INFORMATION



#### Figure 1. Location Map.

## SITE CHARACTERISTICS

| Percent Saturated/Wetland Soils Onsite |           |       |                       | Low:    |        |
|--|-----------|-------|-----------------------|---------|--------|
|  |           |       | USGS Aquifer          | Medium: |        |
|  | 0 to 8%   | 99.7% | Sensitivity           | High:   | 100.0% |
| Slopes Onsite                          | 8 to 12%  | 0.3%  | Drinking Water Well   | Onsite? | No     |
|  | 12 to 15% |       |                       |         |        |
|  | 15 to 20% |       | Soil Contamination    | No      |        |
|  | 20 to 33% |       | UST Onsite?           |         | No     |
|  | > 33%     |       | Septic System Onsite? |         | Yes    |

Note: Not all criteria used in the preliminary BMP site assessments are summarized in this report. For a full list of criteria analyzed for each BMP please see the BMP Preliminary Site Assessment criteria tables.

## PERCENT OF SITE POTENTIALLY NOT SUITABLE FOR BMP IMPLEMENTATION

| Infiltrating<br>Bioretention Cell/Swale | 0% | Permeable Pavement          | On a site by<br>site basis | Underground Detention<br>and Treatment | On a site by<br>site basis |
|---|----|-----------------------------|----------------------------|--|----------------------------|
| Infiltrating<br>Bioretention Planter    | 0% | Ponds and Wetlands          | On a site by site basis    | Aboveground Sand<br>Filtration         | On a site by<br>site basis |
| Non-Infiltrating<br>Bioretention        | 0% | Basic Filter Strips         | On a site by site basis    | Infiltration BMPs                      | On a site by<br>site basis |
|   |    | <b>Biofiltration Swales</b> | On a site by<br>site basis | Dispersion BMPs                        | On a site by<br>site basis |

