



SIDE SEWER INSPECTION FORM

Department of Public Works • Utilities Division

City of Arlington • 154 W. Cox Street • Arlington, WA 98223 • Phone (360) 403-3526

Site Address: 1207 East 5th
 Project Name: Dolores Boyer
 Permit #: 533
 Firm/Developer: _____
 Contact Person: Ken Boyer
 Contractor: _____
 Initial Inspection Date: 1-28-2016

Sewer Permit #: 543
 Lot #: _____
 Phase: _____
 Inspector: Zach Johnson
 Phone: 360-435-2966
 Phone: _____
 Final Inspection Date: 1-28-2016

Staff Comments:
 Side Sewer Repair: 1) Installed 6" C/O @ property line 2) Installed new S/S from 6" C/O to house 3) TV COA 6" stub/stub in great condition

